REMARKS

Status of the Claims

Claims 1-35 are pending in the application, of which Claims 1-7 stand withdrawn

from consideration pursuant to a Restriction Requirement. Claims 8-35 stand rejected.

In view of the following remarks, applicants request re-examination and allowance of the

claims.

Claims 8-35 are Patentable Over Taplan

Claims 8-11 stand rejected under § 102 and claims 12-35 stand rejected under §

103 over Taplan (US 6,032,662). The rejection is respectfully traversed because Taplan

does not bias the supply tube up into a fuel feed port of a burner head.

The cooktop of subject claims 8-24 has a burner box comprising:

"a force member acting against the burner box to bias at least a

portion of the supply tube upwardly into the fuel feed port of the

burner head; "

(Independent Claim 8) Similarly, the cooking device of subject claims 25-35 has a

burner box comprising:

"a force member acting against the burner box to bias at least a

portion of the supply tube upwardly into the fuel feed port of the

burner head; "

(Independent Claim 25). No corresponding feature is found in Taplan. Instead, Taplan

pulls a burner box down against the upper surface of the cooktop or fixes the burner box

to the cooktop and pushes a supply tube up against the bottom of the cooktop.

Response to Final Office Action U.S.S.N. (10/698,581) Page 8 of 10 More specifically, in the embodiment of Fig. 1 of Taplan, spring 4 pulls burner box 9 down onto a top surface of cooktop 1. It does not act against the supply tube at all. This simply is different from the present claim requirement of a force member biasing a

portion of the supply tube upwardly into the fuel feed port of a burner head. There is no

other spring or bias member in Taplan's Fig. 1.

In Taplan's other embodiment, Figs. 2-4, supply tube 19 isn't and can't be biased

upwardly into the fuel feed port of a burner head, because the burner head 9 of Figs. 2-4

has no feed port that contacts the supply tube. Figs. 2-4 show the embodiment described

in Taplan's Summary (col. 3, lines 45-55) where the burner 9 is fixed to the cooktop's

collar, and the bottom opening of the burner is larger than the collar opening:

"...the collar is releasably connected to the gas burner, preferably

with threaded fasteners.

The connection [of the burner to the collar] then takes place via a <u>flange-shaped projection which is formed on the burner</u>. This projection has a smaller diameter than the opening in the cooktop panel but a <u>larger</u> diameter than the diameter of the inner region of the collar of the part of

the assembly engaging from above.

So the burner has no feed port and the supply tube touches no part of the burner.

Instead, spring 7 in Taplan's Figs. 2-4 embodiment pushes supply tube 19 up

against the bottom of the cooktop. This does not meet the present claim requirement of a

force member biasing a portion of the supply tube upwardly into the fuel feed port of a

burner head.

Resilient member 4 in Figs 2-4 does not act against the supply tube at all. It holds

the collar part of the cooktop down against the top of panel 1. Specifically, collar 6 is

connected to transverse member 8 via brackets 11 (called "attachment angles") and

resilient member 4 pulls collar 6 down by pushing transverse member 8 away from

cooktop panel 1.

The Examiner states in the current Office Action, that the Applicant in responding

to the previous Office Action did not address how the claim elements are different from

those [of Taplan] cited by the Examiner in the rejection. Applicant trusts that the above

explanation now clarifies the fundamental deficiencies of Taplan and the patentability of

the subject claims. Where the previous discussion was not precise or correct in certain

respects, the above discussion presents a precise and correct discussion of Taplan and its

differences from the claimed invention. In short, Taplan lacks a force member biasing a

portion of the supply tube upwardly into the fuel feed port of a burner head.

Conclusion

In view of the forgoing, applicant requests that all claims pending in the

application be allowed.

Respectfully submitted,

January 10, 2006

Peter D. McDermott Reg. No. 29,411

Customer No. 28316

Banner & Witcoff, Ltd.

28 State Street, 28th Floor

Boston, MA 02109